

Map 8 Lot 2 and 2.2  
Site Visit  
December 8, 2023


**Minor tree limbing near pond on 8-2**




**Told this pile was from the clearing in another part of the property?**






**Brush cutting in back portion of the property near wooded wetland**





8-2.2





## Map 8 Lot 2.2



